

BUCKLE




Table IV, Defect No. 111, Major defect. Buckle barely extending into side seam.