

BUCKLE



Table IV, Defect No. 111, Major defect. A permanent distortion of a counter sink (channel next to end seam). Cause by excessive internal pressure developed during processing. The distortion of the end seam is readily noticeable at first glance. There is some suspicion that the end seam has been placed under tension sufficient to jeopardize the hermetic seal.