

## OUTSIDE TINPLATE OR COATING (WHEN REQUIRED)



Table IV, Defect No. 204, Minor defect. Outside coating scratched.