

RUST



Table IV, Defect No. 109, Major defect. Pitted rust in deep scratches along side seam. The rust undoubtedly developed in the scratches—a related minor defect.