

## DENT




Table IV, Defect No. 208 - Lower limit of a minor defect. A slight indentation with moderately acute crimping of the body wall resulting in a related minor defect as the end seam is pulled out of position slightly. Must be studied carefully to detect the malposition (minor defect).