

## DENT



Table IV, Defect No. 208 - Upper limit of a minor defect. A moderately deep, sharp, angular indentation with moderately acute crimping of the body wall (minor defect). End seam malposition is so slight that it could be detected only by use of a straight edge or flat surface (no defect).