

DENT




Table IV, Defect No. 110. Major defect. Severe end seam dent likely to affect the usability of the container.